




High Street:








	Property No and Status	Photographs	Note on possible works that may restore historic character
1	No 2 2* 1952		<p>Shopfront works: Replace non traditional signage</p> <p>Possible other works:</p>
2	No 3 & 4 Unlisted		<p>Shopfront works: Overlarge fascia – replace on both with traditional signage</p> <p>Possible other works: Windows – replace with tradition windows</p>
3	No 6 II 1952		<p>Shopfront works: Replace overlarge signage</p> <p>Possible other works:</p>
4	No 7 II 1952		<p>Shopfront works: Replacement of signage Refurish shop front</p> <p>Possible other works: Refurbish windows</p>
5	No 11 – a and b II 1952		<p>Shopfront works: 11 a and 11b – Replacement signage</p> <p>Possible other works: Refurbish windows</p>
6	No 14 II 1952		<p>Shopfront works: Replace fascia signage.</p> <p>Possible other works: Refurbishment of façade and windows.</p>

7	No 17 II 1952			Shopfront works: Replace fascia signage.
				Possible other works: Refurbish windows
8	No 21 II 1952			Shopfront works: Replace fascia signage Replace side door
				Possible other works:
9	No 22 II 1952			Shopfront works: Signage
				Possible other works:
10	No 23 -24 II 1952			Shopfront works: New shopfront
				Possible other works:
11	No 25 II 1952			Shopfront works: Replace non traditional signage
				Possible other works:
12	No 26 Unlisted			Shopfront works: Replace fascia signage Replace shopfront
				Possible other works:






13	No 34 Unlisted		<p>Shopfront works: Replacement signage New shopfront</p>
			<p>Possible other works: Repairs to render Refurbish windows</p>
14	No 35 II 1952		<p>Shopfront works: Empty premises in need of new signage</p>
15	No 36 II 1952		<p>Shopfront works: Signage</p>
			<p>Possible other works: Window refurbishment</p>
16	No 41a		<p>Shopfront works: Replacement signage</p>
			<p>Possible other works:</p>
17	No 43 and 44 II 1952		<p>Shopfront works: 43 - Replace non traditional signage/fascia New shopfront 44 – Refurbishment of shop front</p>
			<p>Possible other works: 43 – Refurbish windows</p>
18	No 45 II 1952		<p>Shopfront works: Replace overlarge fascia sign</p>
			<p>Possible other works: Refurbish upper floor windows</p>

19	No 50 II 1952		Shopfront works: Replace fascia signage
			Possible other works: Refurbish upper floor windows
20	No 56 and 57 II 1952		Shopfront works: 56 – works to shopfront 57 – works to shopfront
			Possible other works: 56 – refurbish upper floors
21	No 104 II 1952		Shopfront works: Works to shopfront/replace non traditional signage
			Possible other works: Refurbish/Replace windows – top floor do not appear to be historic
22	No 105 II 1952		Shopfront works: Refurbish shopfront/replace non traditional signage Replace front door
			Possible other works: Refurbish windows
23	No 106 II 1952		Shopfront works: Replace non traditional signage and awning
			Possible other works: Refurbish windows
24	No 107 II 1952		Shopfront works: Replace overlarge fascia signage
			Possible other works: Refurbish upper floor windows

25	No 108 II 1952		Shopfront works: Replace non traditional signage Reinstate traditional shopfront
			Possible other works: Refurbish windows
26	No 111 II 1952		Shopfront works: Replace non traditional fascia signage and awning/Dutch blind
			Possible other works: Refurbish upper floor windows
27	No 116 II 1973		Shopfront works: Replace non traditional signage Reinstate traditional shopfront
			Possible other works: Refurbish windows
28	No 120 II 1973		Shopfront works: Replace signage
			Possible other works:
29	No 121 II 1952		Shopfront works: Replace non traditional signage Replace doors
			Possible other works:
30	No 122 II 1952		Shopfront works: Replace non traditional awning/Dutch blind
			Possible other works: Refurbish windows
31	No 123 II 1952		Shopfront works: Replace overlarge signage
			Possible other works:



32	No 124 II 1952		Shopfront works: Shop front signage
			Possible other works: Refurbish upper floor windows Façade refurbishment
33	No 130 II 1952		Shopfront works: Replace non traditional signage
			Possible other works:
34	No 147 II 1952		Shopfront works: Shopfront/signage
			Possible other works: Refurbish upper floor windows and dormers
35	No 148 and 149 II 1973		Shopfront works: 148– replace non traditional signage 149 – replace fascia signage
			Possible other works: 148 and 149 - Refurbish upper floor windows
36	No 150 II 1952		Shopfront works: Replace fascia signage Replace shopfront
			Possible other works: Refurbish upper floor windows
37	No 152 II 1952		Shopfront works: Works to fascia
			Possible other works:
38	No 153 II 1952		Shopfront works: Replace fascia signage
			Possible other works:

Church Street:

	Property No and Status	Photographs	Note on possible works that may restore historic character
1	No 3 Unlisted		Shopfront works: Replace non traditional fascia signage
			Possible other works: Replace upper floor windows with timber sashes
2	No 19 II 1952		Shopfront works: Replace non traditional signage
			Possible other works:
3	No 62 II 1952		Shopfront works: Replace signage
			Possible other works: Window refurbishment
4	No 71 II 1952		Shopfront works: Replace non traditional signage
			Possible other works: Dormer repairs
5	No 76 Unlisted		Shopfront works: Replace fascia signage
			Possible other works: Declutter facade
6	No 81 II 1952		Shopfront works: Shop front refurbishment
			Possible other works: Refurbish upper floor windows

7	No 98 II 1970		Shopfront works: Replace non traditional fascia signage
			Possible other works: Window/façade refurbishment
8	No 99 II 1952		Shopfront works: Replace non traditional fascia signage Replace shopfront
			Possible other works:

Barton Street:

	Property No and Status	Photographs	Note on possible works that may restore historic character
1	No 29 II 1952		Shopfront works: Refurbishment of shop fronts
			Possible other works: Side gable repairs Shop front
2	Nos 42 and 43 II 1952		Shopfront works: Replace non traditional signage
			Possible other works: Refurbish first floor windows. Replace top floor windows
3	Nos 55 and 56 Unlisted		Shopfront works: Replace fascia signage with individually applied lettering.
			Possible other works: Reinstate first floor sashes
4	No 75 II 1952		Shopfront works: Replace non traditional signage
			Possible other works:

5	No 76 II 1994		<p>Shopfront works: Replace non traditional signage Remove additional fascia and additional text.</p> <p>Possible other works:</p>
6	Nos 81 and 82 II* 1952		<p>Shopfront works: Replace non traditional signage</p> <p>Possible other works: Refurbish front elevation</p>
7	Nos 84 and 84a II 1952		<p>Shopfront works: Replace non traditional fascia signage Replace modern door</p> <p>Possible other works:</p>